

BOQ for Rehabilitation of Charbagh CHC

HF N	S/No	ACTIVITIES	Unit	Quantity	Unit Cost Af	Total Cost Af	Remarks
Charbagh CHC 1	1	Compaction and leveling of old Clay and spread one layer of low Quality plastic	M ²	110.00			
	2	PCC ccement concrete for Roof ,Gravel , local Laghman yelo send and M ; !00 1:3:6 ,Thickness = 4cm	M ²	60.00			
	3	Roofing ; Supply and Installationone layer Bituminous (Isogam) waterproofed, one Roll 40kg L= 10meter and W=1meter with all related works for roof.	M ²	115.00			
	4	Supply and installation of best Quality 1000 liter plastic water tank with with all required activities:	piece	1.00			
	5	Replacement of tap , mixer, and extra pipe for sink and water tank of commode with all required activities:	set	10.00			
		GRAND TOTAL					

BOQ for Rehabilitation Omarzai SHC

HF N	S/No	ACTIVITIES	Unit	Quantity	Unit Cost Af	Total Cost Af	Remarks
Omarzai SHC 2	1	Delivery Room Installation and suply of Floor tile 50x50 ceramic whith all respected works	M ²	23.00			
	2	Delivery Installation and suply of Wall tile 30x60 And rmoveing of wall Paint	M ²	25.00			
	3	Supply replacement and rpiaring of canalization and water supply system installation water tap, piping all related valve ,Tee , elbow, and joint based on the need and with all required activities.	LMS/Jop	3.00			building indoor and outdoor canalization
	4	Pit : Excavation of hole for Incinerator 1.2x1.2x3.5 meter and with all equired activities:	M ³	7.00			
	5	back filling of outside of hole specification with all equired activities:	M ³	5.00			
	6	Pcc concrete for (Pit) Hole m=100	M ³	1.00			
	7	RCC slabinbg thickness =10 cm concrete for pit (hole cover) with small iron door 35x35cm cover with all required activities.,	piece	3.00			
	8	plaster and filling for inside wall for (Pit) Hole M=100	M ²	100.00			
	9	stone masonry without Mortar specification and all required activities:	M ³	35.00			

	10	Area description for Eschew fence Installation, must be have after every two meter an iron column D=2"inch , H=2meter reduced in PCC concrete , gage 18 and thickness 1.5 mm , the Eschew 3mm fence every one frame 1.5x2 meter mast be have around 0.75" inch Angle iron main door with weld works for related HF .	M ²	18.00			this includes waste pits and fence construction
		GRAND TOTAL					

BOQ for Rehabilitation Chapa darya SHC

HF N	S/No	ACTIVITIES	Unit	Quantity	Unit Cost Af	Total Cost Af	Remarks
Chapa Drya SHC 4	1	Compaction and leveling of old Clay and spread one layer of high Quality plastic	M ²	120.00			
	2	Straw clay (mud plaster) of roof Thickness 3.5cm , straw =1kg/meter	M ²	120.00			
		GRAND TOTAL					

BOQ for Rehabilitation of Katal BHC

HF N	S/No	ACTIVITIES	Unit	Quantity	Unit Cost Af	Total Cost Af	Remarks
Katal BHC 8	1	making and enstallation wooden window 0.7x1 meter with all respected works	piece	2.00			
	2	for Wooden window & Door replicement and repiaring of all respected as lock , hinge , glass hand hangar and installation, accessories and Aluminum Fly Screens	piece	8.00			
	3	roof cover with wooden board plastic and clay +gutter for bathroom and pit	M ²	20.00			
	4	Supply replacement and installation water tap, piping all related valve ,Tee , elbow, and joint based on the need and with all required activities.	set	2.00			
		GRAND TOTAL					

BOQ for Rehabilitation of Mehtarlam CHC

HF N	S/No	ACTIVITIES	Unit	Quantity	Unit Cost Af	Total Cost Af	Remarks
Mehtarlam CHC 15	1	some bathroom replacement and Installation and supply of Floor tile ceramic whith all respected works	M ²	18.00			
	2	PCC : Vaccine Room and new bathroom PCC With M150 for room and wak way and all required activities	M ³	3.00			
	3	Supply replacement and installation water tap, piping all related valve ,Tee , elbow, and joint based on the need ,outside main hand hole and with all required activities.	LMS	3.00			
		GRAND TOTAL					

BOQ for Rehabilitation Dewa BHC

HF N	S/No	ACTIVITIES	Unit	Quantity	Unit Cost Af	Total Cost Af	Remarks
Dewa BHC 16	1	Delivery Room Installation and supply of Floor tile 50x50 ceramic whith all respected works	M ²	22.00			
	2	Delivery Installation and supply of Wall tile 30x60 And rmoveing of wall Paint	M ²	27.00			
	3	Supply and installation of,6socket , 6 holder , 6 light 24w , swatch , one fuse with all wiring and with all required activities.	LMS job	2.00			
	4	compaction and leveling of old Clay and spread one layer of low Qualty plastic	M ²	180.00			
	5	PCC ccement concrete for Roof ,Gravel , local Laghman yellow send and M ; !00 1:3:6 ,Thickness = 5cm	M ²	180.00			
	6	Roofing ; Supply and Installationone layer Bituminous (Isogam) waterproofed, one Roll 40kg L= 10meter and W=1meter with all related works for roof.	M ²	190.00			
		GRAND TOTAL					

BOQ for Rehabilitation of Kashmond BHC

HF N	S/No	ACTIVITIES	Unit	Quantity	Unit Cost Af	Total Cost Af	Remarks
Kashmond BHC 23	1	Compaction and leveling of old Clay and spread one layer of low Quality plastic	M ²	150.00			
	2	PCC cement concrete for Roof ,Gravel , local Laghman yelo send and M ; !00 1:3:6 ,Thickness = 5cm	M ²	150.00			
	3	Roofing ; Supply and Installationone layer Bituminous (Isogam) waterproofed, one Roll 40kg L= 10meter and W=1meter with all related works for roof.	M ²	160.00			
		GRAND TOTAL					

BOQ for Rehabilitation of Aziz khan Kas BHC

HF N	S/No	ACTIVITIES	Unit	Quantity	Unit Cost Af	Total Cost Af	Remarks
Azizkhan kas BHC 26	1	Compaction and leveling of old Clay and spread one layer of low Quality plastic	M ²	100.00			
	2	PCC cecement concrete for Roof ,Gravel , local Laghman yelo send and M ; !00 1:3:6 ,Thickness = 5cm	M ²	100.00			
	3	Roofing ; Supply and Installationone layer Bituminous (Isogam) waterproofed, one Roll 40kg L= 10meter and W=1meter with all related works for roof.	M ²	100.00			
	4	Making of new main hand hole inastallation of cover 40x40	piece	8.00			
	5	Repairing and Replacement of tap ,mixet , extrapipe , net of hole and shower with all respected works	LMS Jop	4.00			
	6	Making of new Canalizations and water supply system complete bisan (sink) Siphon and Piping jointe to outside mainhole with all respected works	Jop	1.00			
		GRAND TOTAL					

BOQ for Rehabilitation of Zafaran SHC

HF N	S/No	ACTIVITIES	Unit	Quantity	Unit Cost Af	Total Cost Af	Remarks
Zafaran SHC 27	1	Leveling of roof and spread 2 layer of plastic best Quality	M ²	280.00			
	2	straw clay (mud plaster) of roof Thickness 3.5cm , straw =1kg/meter	M ²	280.00			
	3	Installation precast slab 05x100 cm for parapet with all related works for roof.	piece	70.00			
		GRAND TOTAL					

BOQ for Rehabilitation of Qarghayee CHC

HF N	S/No	ACTIVITIES	Unit	Quantity	Unit Cost Af	Total Cost Af	Remarks
Qarghayee CHC 28	1	Compaction and leveling of old Clay and spread one layer of low Quality plastic	M ²	100.00			
	2	PCC cement concrete for Roof ,Gravel , local Laghman yelo send and M ; !00 1:3:6 ,Thickness = 4cm	M ²	100.00			
	3	Roofing ; Supply and Installationone layer Bituminous (Isogam) waterproofed, one Roll 40kg L= 10meter and W=1meter with all related works for roof.	M ²	400.00			
	4	Plastering for wall inside outside (M=1:6) and based on the design, and specification with all required activities:	m2	100.00			
	5	Repiaring : Wooden Door and window frame and opening part , Repiaring with all respected as lock , hinge , glass hand hangar and installation, accessories and Aluminum Fly Screens	Piece	10.00			
		GRAND TOTAL					

BOQ for Rehabilitation of Ghondi SHC

HF N	S/No	ACTIVITIES	Unit	Quantity	Unit Cost Af	Total Cost Af	Remarks
Ghondi SHC	1	Making of new main hand hole in installation of cover 40x40	piece	6.00			
	2	Area description for Eschew fence Installation, must be have after every two meter an iron column D=2"inch , H=2meter reduced in PCC concrete , gage 18 and thickness 1.5 mm , the Eschew 3mm fence every one frame 1.5x2 meter must be have around 0.75" inch Angle iron main door with weld works for related HF .	M ²	20.00			
		GRAND TOTAL					

BOQ for Rehabilitation of kanda BHC

HF N	S/No	ACTIVITIES	Unit	Quantity	Unit Cost Af	Total Cost Af	Remarks
Kanda BHC 33	1	RCC slabinbg thickness =10 cm concrete for pit (hole cover) with small iron door 35x35cm cover	M2	3.00			
	2	Repiaring : Wooden Door and window frame and opaning part , Repiaring with all respected as lock , hinge , glass hand hangar and installation, accessories and Aluminum Fly Screens	Piece	8.00			
	3	Supply replacement and repiaring , installation tap, piping all related valve ,Tee , elbow, and joint based on the need and with all required activities.	LMS	6.00			
	4	PCC : PCC With M150 for room and wak way and all required activities	M ³	3.50			
		GRAND TOTAL					

BOQ for Rehabilitation of Karanch SHC

HF N	S/No	ACTIVITIES	Unit	Quantity	Unit Cost Af	Total Cost Af	Remarks
Karanch SHC 34	1	RCC slabinbg thickness =10 cm concrete for pit (hole cover) with small iron door 35x35cm cover ,installation of iron pipe 3" h=1meter	m2	6.00			
	2	Supply replacement and repiaring , installation tap, piping all related valve ,Tee , elbow, and joint based on the need and with all required activities.	LMS	3.00			
		GRAND TOTAL					

BOQ for Rehabilitation of Gularam SHC

HF N	S/No	ACTIVITIES	Unit	Quantity	Unit Cost Af	Total Cost Af	Remarks
Gularam SHC 35	1	Delivery Room Installation and suply of Floor tile 50x50 ceramic whitth all respected works	M ²	27.00			
	2	Delivery Installation and suply of Wall tile 30x60 And rmoveing of wall Paint	M ²	30.00			
	3	One room repairing (plaster , painting ,tiling and water sapply system)	LMS	1.00			
		GRAND TOTAL					

BOQ for Rehabilitation of Shamati BHC

HF N	S/No	ACTIVITIES	Unit	Quantity	Unit Cost Af	Total Cost Af	Remarks
Shamati BHC 38	1	Repiaring : painting ,plastering and small rehabilitation for floor for bathroom	LMS	2.00			
		GRAND TOTAL					

BOQ for Rehabilitation of Zirani SHC

HF N	S/No	ACTIVITIES	Unit	Quantity	Unit Cost Af	Total Cost Af	Remarks
Zirani SHC 39	1	Making of new canalization system piping pipe 5" and joint with min hole and side mast be cover with bricks and plaster	meter	20.00			
	2	Making of new main hand hole inastallation of cover 40x40	piece	5.00			
		GRAND TOTAL					

BOQ for Rehabilitation of Alishing BHC

HF N	S/No	ACTIVITIES	Unit	Quantity	Unit Cost Af	Total Cost Af	Remarks
Alishing BHC 40	1	Compaction and leveling of old Clay and spread one layer of low Quality plastic	M ²	240.00			
	2	PCC cccement concrete for Roof ,Gravel , local Laghman yelo send and M ; !00 1:3:6 ,Thickness = 3cm	M ²	240.00			
	3	Roofing ; Supply and Installationone layer Bituminous (Isogam) waterproofed, one Roll 40kg L= 10meter and W=1meter with all related works for roof.	M ²	300.00			
	4	Repairing and Replacement of Canalizations system Outsidi insid Siphon and Piping Instalation to outside mainhole with all respected works	LMS Jop	3.00			
	5	Removing and Reinstalation of old main iron Door with all brick masonry and welding works	piece	1.00			
		GRAND TOTAL					

BOQ for Rehabilitation of Surkhakan CHC

HF N	S/No	ACTIVITIES	Unit	Quantity	Unit Cost Af	Total Cost Af	Remarks
Surkhakan CHC 41	1	Supply and installation of energy sewar light 40 W	piece	30.00			
	2	Supply installation of holder 40 W	piece	30.00			
	3	Supply replacement of water filter with installation water tap, piping all related valve ,Tee , elbow, and joint based on the need ,outside main hand hole and with all required activities.	jop	2.00			
	4	Supply replacement of PVC pipe 5", outside main hand hole repiarin , with all required activities.	meter	5.00			
	5	Iron sheet : installation Profile Thickness 1.2mm D=3"x1.5" Inch) and replcement of iron metallic 0.5mm Sheet for roof on the top of frame with respected works	m2	6.00			
	6	Plastic and oil paint with all required activities:	m2	40.00			
		GRAND TOTAL					